

# **Making the Best of a Bad Situation: From leaking UST Over Fractured Bedrock with Closed Municipal Wells to Case Closure – A Success Story**



Warren Gross, P.G., C.E.G., C.H.G.


Jeff Hannel, P.G., C.H.G.

CRWQCB – Region 5, Fresno

# Facility Location



# Site Map



Site Photo




# UST Removals

## March 1999

TPHg 160 mg/kg  
Benzene 0.5 mg/kg  
MTBE 120 mg/kg



# YLP Aerial



FRIDAY  
JULY 21, 2000

# The Fresno Bee

50 CENTS

CENTRAL CALIFORNIA'S LEADING NEWSPAPER FOR 77 YEARS

[www.fresnobee.com](http://www.fresnobee.com)

## Source of Madera well contamination sought

Testing is under way on grounds of suspected leakers.

By JIM DAVIS  
THE FRESNO BEE

**COARSEGOLD** — State water-quality officials are trying to determine the cause — and the extent — of contamination by a fuel additive that forced the closure of the main water well for the large-

est subdivision in eastern Madera County.

The additive known as MTBE was found last month in the well at Yosemite Lakes Park, about seven miles south of Coarsegold.

"There's hope that this is not a large problem," said John Noonan of the Cen-

tral Valley Regional Water Quality Control Board in Fresno. "But it doesn't mean that it isn't."

The well is one of 16 for Yosemite Lakes Park, which has 1,400 homes and more than 3,000 residents.

Yosemite Springs Park Utility — the water company that provides water to the park — shut down the well as soon as the contamination was found, said Ken Harrington, the company's manager.

The company has been able to keep water pressure flowing normally, but Harrington is concerned about the loss.

"This well has always been what we referred to as our bread-and-butter well," Harrington said. "It's the only well — up until this happened — that we ran 365 days of the year."

MTBE, or methyl tertiary-butyl ether, is a gasoline octane booster designed to reduce air pollution. But research has in-

dicated MTBE could cause cancer. In some areas of the state, leaking gasoline tanks have allowed MTBE to creep into surface and ground water.

Last year, the Yosemite Lakes Trading Post replaced three gasoline tanks — one with a 4,000-gallon capacity and two with room for 2,000 gallons — as it upgraded to meet new standards.

As the tanks were being removed, a  
Please see **LAKES**, Page A20

# Impacted Supply Wells





# Well 37A Log

(12) WELL LOG: Total depth <u>0</u> ft. Depth of completed well <u>675</u> ft.		from ft.	to	ft. Formation (Describe by color, character, etc. as unusual)
0	-	12		Overburden
12	-	30		Gray granite
30	-	35		Broken rock
172	-			Break
206	-	209		Broken rock
217	-	221		Serpentine seam
221	-	275		Black & white granite
275	-	296		Gray granite
296	-	338		Black & white granite
331	-	332		Quartz
338	-	358		White granite
358	-	361		Broken gray granite
361	-	401		Gray granite
401	-	410		White granite
410	-	440		Gray granite
430	-	440		Broken gray granite
440	-			Black & white granite
441	-	445		Broken black & white granite (Serpentine seam)
446	-			Serpentine seam
456	-	458		Broken black & white granite (first water)
471	-			Break
491	-			Break
519	-			Break

# Assessment Objectives

- Complete an expedited site assessment
  - Characterize geology and hydrogeology
  - Assess distribution of contaminants of concern
  - Develop a remedial strategy

# Geologic Map



Kk


Granodiorite of Knowles

Kw

Leucotonalite of  
Ward Mountain

Kbl

Tonalite of  
Blue Canyon



Intrusive Breccia

USGS Geologic Quadrangle  
Maps GQ1548 & GQ1555

# Potential Faults






# Lineaments



# Soil Assessment



# Soil Borings & Shallow Wells





# Cross-Section A-A'




**LEGEND** (ANALYTICAL RESULTS IN mg/kg)

240 — TPH-G      13 — MTBE      ND — NOT DETECTED  
 300 — Benzene      10 — TBA      NA — NOT ANALYZED


----- ESTIMATED EXTENT OF GASOLINE CONSTITUENTS




# Geophysical Survey Locations




# Seismic Profile Interpretation



# Regional Groundwater Contours



# Deep Well Locations







# MW-101 Video Log

- 1) Well ID on top is 6 1/4".
- 2) Zero datum marked at top of casing. All side view depths are 18" less than indicated on monitor.
- 3) 18' Casing seam.
- 4) 38' End of the casing. Open bore hole in granite below this point.
- 5) 53' Ruff or loose formation.
- 6) 60', 71', 75' Small fractures
- 7) 78' Fracture with loose rock.
- 8) 82' Static water level.
- 9) 84' Fracture in rock.
- 10) 85' Yellowish growth on the granite.
- 11) 90' Small fracture.
- 12) 96'-98' White rock formation.
- 13) 101' Large fracture.
- 14) 107' Vertical fracture in rock.
- 15) 153' Change in formation. Also appears to be some type of growth developing in this area down to approx. 162'.
- 16) 162', Fracture in the rock.
- 17) 205', 210' Small fracture in the rock.
- 18) 221' Fracture with what appears to be the same growth as above.
- 19) 236' White formation.
- 20) 247' Bottom of the well.

# Site Groundwater Contours



# Benzene/MTBE/TBA in Groundwater, December 2000




# Packer Testing






# YSPUC Water Quality




# MW-101 Water Quality



# MTBE/TBA in MW-101 Fractures

Fracture Depth Ft / Yield (gpm)	MTBE(ug/L)	TBA (ug/L)
77 / 1.5	2,500	<2,000
87 / 0.8	2,800	<4,000
103 / 3.3	3,300	<4,000
152 / 0.08	1,600	<1,000
162 / 3.5	430	<1,000
208 / 2.25	260	4.2
220 / 4.0	820	<1,000

# GW response to Packer Testing







# Aquifer test

- 48-hour
- MTBE/TBA 1,200/2,600 ug/L after 24 hrs
- MTBE/TBA 997/2,200 ug/L after 48 hrs

# Distance-Drawdown Relationships



# Radius of Influence – Pumping from MW-101



# Assessment Conclusions

- The extent of petroleum hydrocarbons has been defined. Vadose zone remediation should be evaluated by expedited soil vapor extraction using existing wells.
- Little groundwater is present within the alluvial/DG aquifer.
- Petroleum hydrocarbons and MTBE have passed readily into the bedrock aquifer.
- The extent of MTBE/TBA distribution has not been fully defined, but assessment is sufficient to facilitate interim remediation.
- Petroleum hydrocarbons appear to be degrading by natural attenuation.



# Assessment Conclusions 2

- MTBE is relatively persistent within the aquifer, degrading slowly to TBA as oxygen is available and likely assisted by leachfield bacteria.
- MW-101 is well connected hydraulically to the MTBE plume from the station, as well as to the fault water supply feeding the impacted water supply wells.
- Groundwater extraction from MW-101 on a continuous basis at a rate of approximately 10 gpm appears feasible and is recommended.
- On site treatment for the produced water should be provided prior to discharge.

Site assessment completed,  
interim soil remediation  
underway, and report submitted  
with recommendations for  
groundwater remediation  
- in 7 months.

All assessment and interim remedial costs  
pre-approved and reimbursed by the UST  
Cleanup Fund.

# SVE




# Air Stripper





# GW Remediation



# GAC



# Nutrient Injection



# UV Disinfection






# GW Treatment System




# MW-101

MW-101 MTBE/TBA




# Airstripper TBA Concentrations



# MW-103 MTBE/TBA

MW-103 MTBE/TBA






# Wellhead Treatment – 37A





# MTBE 37A/40A



# Regulatory and UST Cleanup Fund Considerations

- Close Communication is critical to Expedited site Assessment
  - Verbal updates to Regional Water Board
  - Field observations by Regional Water Board
  - E-mail pre-approval requests to Cleanup Fund